



Příloha č. 4 Seznam zařízení pro poskytovaný servis

Název veřejné zakázky:

Support aktivních prvků LAN SFŽP

Identifikační údaje zadavatele:

Název: Státní fond životního prostředí České republiky
IČ: 00020729
Adresa sídla: Kaplanova 1931/1, Praha 11 – Chodov, PSČ 148 00
Korespondenční adresa: Olbrachtova 2006/9, Praha 4, PSČ 140 21

| Produktové číslo prvku | Sériové číslo | Název prvku | Popis SLA | Doba podpory v této nabídce (měsíců) | Konec podpory (daného prvku i mimo tuto nabídku) |
|------------------------|---------------|-------------|-----------|--------------------------------------|--|
|------------------------|---------------|-------------|-----------|--------------------------------------|--|

| | | | | | |
|--------------------|-------------|----------------|-------------------------------|----|-----------|
| WS-C3560G-48TS-S | FOC1245W1MB | SFZP-BUD-ASW3B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1245W1H1 | SFZP-BUD-ASW6B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1245W1H7 | SFZP-BUD-ASW3A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1245W1H5 | SFZP-BUD-SPARE | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1245W1M9 | SFZP-BUD-DSW5C | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1245W1N5 | SFZP-BUD-ASW5A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1245W1N2 | SFZP-BUD-DSW5D | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3750G-24WS-S25 | FOC1245G004 | SFZP-BUD-ASW4W | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C4506-E | FOX1235GSCT | SFZP-BUD-DSW5A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| X2-10GB-CX4 | OSG12280210 | SFZP-BUD-DSW5A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-X4506-GB-T | JAE1241WX00 | SFZP-BUD-DSW5A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-X4424-GB-RJ45 | JAE1244Z7ZI | SFZP-BUD-DSW5A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| PWR-C45-1400AC | AZS12430M92 | SFZP-BUD-DSW5A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| PWR-C45-1400AC/2 | AZS12430M90 | SFZP-BUD-DSW5A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-X45-SUP6-E | JAE1245ZC82 | SFZP-BUD-DSW5A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C4506-E | FOX1236GC9D | SFZP-BUD-DSW5B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| X2-10GB-CX4 | OSG12293804 | SFZP-BUD-DSW5B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-X4506-GB-T | JAE1235T1GG | SFZP-BUD-DSW5B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |

| | | | | | |
|--------------------|-------------|-------------------|------------------------------------|----|-----------|
| WS-X4424-GB-RJ45 | JAE1244Z7XE | SFZP-BUD-DSW5B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| PWR-C45-1400AC | AZS12430M8T | SFZP-BUD-DSW5B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| PWR-C45-1400AC/2 | AZS12430M9H | SFZP-BUD-DSW5B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-X45-SUP6-E | JAE12460CGG | SFZP-BUD-DSW5B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| NAC3310-250FB-K9 | 1521J226E63 | SFZP-BUD-NACMGR+2 | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| NAC3310-SVR | FTX1249501W | SFZP-BUD-NACMGR | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| NAC3310-SVR | FTX1249501X | SFZP-BUD-NACMGR2 | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| NACMGR-3FB-K9 | 1521J558CBD | SFZP-BUD-NACAPP+2 | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| NAC3310 | FTX1249501Z | SFZP-BUD-NACAPP | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| NAC3310 | FTX1249501Y | SFZP-BUD-NACAPP2 | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| ASA5510-AIP10-K9 | JMX1249L0CL | SFZP-BUD-ASA2 | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| ASA5510-AIP10-K9 | JMX1249L0CL | SFZP-BUD-ASA2 | Uptime Subscription Services Admin | 12 | 31.5.2014 |
| ASA-AIP-10-INC-K9 | JAF1242BNQR | SFZP-BUD-ASA2 | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| ASA-AIP-10-INC-K9 | JAF1242BNQR | SFZP-BUD-ASA2 | Uptime Subscription Services Admin | 12 | 31.5.2014 |
| ASA5510-AIP10-K9 | JMX1249L0PP | SFZP-BUD-ASA1 | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| ASA5510-AIP10-K9 | JMX1249L0PP | SFZP-BUD-ASA1 | Uptime Subscription Services Admin | 12 | 31.5.2014 |
| ASA-AIP-10-INC-K9 | JAF1242AJGF | SFZP-BUD-ASA1 | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| ASA-AIP-10-INC-K9 | JAF1242AJGF | SFZP-BUD-ASA1 | Uptime Subscription Services Admin | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1323Q0LM | SFZP-BUD-AP5D | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1323Q0LY | SFZP-BUD-AP5C | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1325Z2ZG | SFZP-BUD-ASW5B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1335Y0EE | SFZP-BUD-ASW5C | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1335Y0AC | SFZP-KAP-IDF1-SW1 | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1335Y0C6 | SFZP-BUD-ASW5E | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1335Y0BY | SFZP-BUD-ASW3C | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| PWR-C45-1300ACV= | DTM140600P9 | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| WS-C4506E-S6L-1300 | FOX1416GXBF | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| WS-X4648-RJ45V+E | JAE14220IFR | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| WS-X45-SUP6L-E | JAE142209TM | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| PWR-C45-1300ACV | DTM141603VH | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| CVR-X2-SFP | FDO14190B40 | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| CVR-X2-SFP | FDO14190E2Q | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| WS-X4648-RJ45V+E | JAE14220IE6 | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| GLC-T= | MTC142007ND | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| GLC-T= | MTC142004NP | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| GLC-T= | MTC142007S1 | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| GLC-T= | MTC142003SN | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| GLC-SX-MM= | FNS14190L7Z | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |

Handwritten initials/signature

| | | | | | |
|--------------------|-------------|--------------------|------------------------------------|----|-----------|
| GLC-SX-MM= | FNS14190L76 | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| GLC-SX-MM= | FNS142001RM | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| GLC-SX-MM= | FNS142001RD | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| PWR-C45-1300ACV= | SNI1417AS6W | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| WS-X4648-RJ45-E= | JAE142400VQ | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| WS-X4648-RJ45-E= | JAE142400VD | SFZP-BUD-ASW4A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| WS-C4506E-S6L-1300 | FOX1426H066 | SFZP-BUD-ASW2A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| WS-X4648-RJ45V+E | JAE14270PUO | SFZP-BUD-ASW2A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| WS-X45-SUP6L-E | JAE142808WK | SFZP-BUD-ASW2A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| PWR-C45-1300ACV | SNI1424AVL7 | SFZP-BUD-ASW2A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| CVR-X2-SFP | FDO14261LBE | SFZP-BUD-ASW2A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| CVR-X2-SFP | FDO142604MU | SFZP-BUD-ASW2A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| WS-X4648-RJ45V+E | JAE14270Q4E | SFZP-BUD-ASW2A | Uptime Reconfigure Response 8*x5x4 | 9 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SR | SFZP-BUD-AP3C | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SN | SFZP-BUD-AP3A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SM | SFZP-BUD-AP4D | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0T2 | SFZP-BUD-AP5A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0T1 | SFZP-BUD-AP5B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SV | SFZP-BUD-AP4B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SW | SFZP-BUD-AP4A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0ST | SFZP-BUD-AP2A | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SY | SFZP-BUD-AP4C | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0T0 | SFZP-BUD-AP2C | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SZ | SFZP-BUD-AP2B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SX | SFZP-BUD-AP2D | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SQ | SFZP-BUD-AP3B | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| AIR-LAP1131AG-E-K9 | FCZ1248Q0SP | SFZP-BUD-AP3D | Uptime Ship Response 8*x5xNBD | 12 | 31.5.2014 |
| WS-C4506E-S6L-1300 | FOX1529G7RB | SFZP-BUD-ASW9A | Uptime Reconfigure Response 8*x5x4 | 0 | 3.11.2014 |
| WS-X4648-RJ45V+E | JAE153400YM | SFZP-BUD-ASW9A | Uptime Reconfigure Response 8*x5x4 | 0 | 3.11.2014 |
| WS-X45-SUP6L-E | JAE153400BE | SFZP-BUD-ASW9A | Uptime Reconfigure Response 8*x5x4 | 0 | 3.11.2014 |
| PWR-C45-1300ACV | SNI1530ATD1 | SFZP-BUD-ASW9A | Uptime Ship Response 8*x5xNBD | 0 | 3.11.2014 |
| CVR-X2-SFP | FDO15321X5H | SFZP-BUD-ASW9A | Uptime Reconfigure Response 8*x5x4 | 0 | 3.11.2014 |
| CVR-X2-SFP | FDO153221CZ | SFZP-BUD-ASW9A | Uptime Reconfigure Response 8*x5x4 | 0 | 3.11.2014 |
| WS-X4648-RJ45V+E | JAE153400Z4 | SFZP-BUD-ASW9A | Uptime Reconfigure Response 8*x5x4 | 0 | 3.11.2014 |
| AIR-WCS-WB-1.0-K9 | 11910314AE0 | SFZP-BUD-ASW4W WLC | Uptime Upgrades & Vendor Support | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1352Z5QT | SFZP-BUD-ASW3D | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1352Z5RH | SFZP-BUD-ASW5D | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| WS-C3560G-48TS-S | FOC1344Y43S | SFZP-KAP-MDF1-SW1 | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |

| | | | | | |
|-------------------|--------------|----------------------------|---------------------------------------|----|------------|
| WS-C3560G-48TS-S | FOC1352Z5RS | SFZP-BUD-ASW6A | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX164540GP | SFZP-KP-BRNO | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1645Z0QG | SFZP-KP-CB | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX164540GL | SFZP-KP-HK | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX164540GN | SFZP-KP-JIHLAVA | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX164540GQ | SFZP-KP-KV | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1645Z0QH | SFZP-KP-KLADNO | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1645Z0QF | SFZP-KP-LIBEREC | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1645Z0QE | SFZP-KP-OLOMOUK | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1645Z0QC | SFZP-KP-OSTRAVA | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1645Z0QB | SFZP-KP- PARDUBICE | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1629Z0S5 | SFZP-KP-PLZEN | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1629403V | SFZP-KP-UL | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1640Z1ZG | SFZP-KP-ZLIN | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| ASA5505-50-BUN-K9 | JMX1640Z1ZF | SFZP-KP-SPARE | Uptime Reconfigure Response 8*x5x4 | 12 | 31.5.2014 |
| FPC-ADS-102 | | SFZP-FLOWMON- ADS | Vendor Service No Call Management | 0 | 30.11.2014 |
| IFC-R5-2000 | | SFZP-FLOWMON- COLLECTOR | Vendor Service No Call Management | 0 | 30.11.2014 |
| IFP-4000-CU | AZGP94300399 | SFZP-FLOWMON | Vendor Service No Call Management | 0 | 30.11.2014 |